

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number K08037400	2. Page 1 of 1	3. Emergency Response Phone 781-237-1234	4. Manifest Tracking Number 008037400 FLE		
5. Generator's Name and Mailing Address 2549 North New York Street Wichita, KS 67219 (316) 266-7400			Generator's Site Address (if different than mailing address) SAME				
6. Transporter 1 Company Name Tyrone P. ...			U.S. EPA ID Number 041000003 3087				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address 40355 S County Road 230 Wichita, OK 73060 (580) 697-3500			U.S. EPA ID Number 040065438376				
Facility's Phone:							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any)) HAZARDOUS WASTE, SOLID, N.O.S. (POB, POB, D, POB III)	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	1.		1	DT	EST 16	Y	1001 1002 1003 1004 1005
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information 1. CH891502X08 ERG#171 JIM TYSON TRF 1113 TLH#6005							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Jim Tyson							
Signature Jim Tyson							
Month Day Year 2 12 13							
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name Stamper						
	Signature Stamper						
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number						
	Facility's Phone:						
	18c. Signature of Alternate Facility (or Generator)						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H132		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name							
Signature							
Month Day Year							

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number K 31007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037400 FLE	
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 285-7400			Generator's Site Address (if different than mailing address) SAME			
6. Transporter 1 Company Name Basin Environmental			U.S. EPA ID Number OKR000023085			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Harbors Long Mountain LLC 40355 S County Road 236 Wannoka, OK 73090 (580) 697-3500			U.S. EPA ID Number OKR0065438376			
Facility's Phone:						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.
			No.	Type		
	x	1. HAZARDOUS WASTE, SOLID, N.O.S. (F001, F005), 9, PG III	1	DT	EST 16	Y
		2.				
		3.				
		4.				
13. Waste Codes F001 F002 F003 F004 F005						
14. Special Handling Instructions and Additional Information 1. CH31502X08 ERG1171 JIM TYSON TR# 1113 TL#E025						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Offor's Printed/Typed Name Jim Tyson			Signature Jim Tyson		Month Day Year 2/12/15	
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:					
	17. Transporter Acknowledgment of Receipt of Materials					
TRANSPORTER	Transporter 1 Printed/Typed Name Rick A. Stamer			Signature Rick A. Stamer		Month Day Year 2/12/15
	Transporter 2 Printed/Typed Name			Signature		Month Day Year
DESIGNATED FACILITY	18. Discrepancy					
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection					
	18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number					
	Facility's Phone:					
	18c. Signature of Alternate Facility (or Generator) Month Day Year					
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H132		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						15-1439
Printed/Typed Name David Raul			Signature David Raul		Month Day Year 2/12/15	